

BACK DOOR CLOSER SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

059XN-01

HINT:

Troubleshoot in accordance with the procedures on the following pages.

1 VEHICLE BROUGHT TO WORKSHOP



2 CUSTOMER PROBLEM ANALYSIS CHECK AND SYMPTOM CHECK (See page 05-1 142)



3 INSPECT COMMUNICATION FUNCTION OF LARGE-SCALE MULTIPLEX COMMUNICATION SYSTEM (BEAN)

- (a) Check that there is no abnormality in the communication system by inspecting the communication function of the multiplex communication system with the hand-held tester.
- (1) (ECU unconnected, communication line abnormal) Without code outputs, proceed to A.
 - (2) (ECU unconnected, communication line abnormal) With code outputs, proceed to B.

B

GO TO BODY MULTIPLEX COMMUNICATION SECTION (See page 05-1268)

A

4 DIAGNOSTIC TROUBLE CODE CHECK (See page 05-1 171)

- (a) Check the diagnostic trouble code.
- (1) Without code outputs, proceed to A.
 - (2) With code outputs, proceed to B.

B

Go to step 6

A

5 PROBLEM SYMPTOMS TABLE (See page 05-1 173)

- (a) Without applicable symptoms, proceed to A.
- (b) With applicable symptoms, proceed to B.

B

Go to step 6

A

6	PERFORM TROUBLESHOOTING IN FOLLOWING METHOD, DEPENDING ON MALFUNCTION SYMPTOM
----------	--

- (a) Pre-check (See page [05-1 143](#))
- (1) Inspection with the hand-held tester (ECU DATA LIST)
 - (2) Inspection with the hand-held tester (ACTIVE TEST)
- (b) On-vehicle inspection (See page [73-9](#)).
- (c) Inspection (See page [73-3](#)).
- (d) Terminals of ECU (See page [05-1 147](#)).



7	ADJUST, REPAIR OR REPLACE
----------	----------------------------------



END
