

SOUND QUALITY IS BAD ONLY WHEN CD IS PLAYED (VOLUME IS TOO LOW)

INSPECTION PROCEDURE

1 REPLACE CD WITH ANOTHER AND RECHECK

- (a) Replace the CD with another and recheck.
(1) Check the installation condition of the radio receiver assembly.

Standard: malfunction disappear.

NG

CD FAULTY

OK

CHECK AND REPLACE RADIO RECEIVER ASSY